

# **Bat Safe Roofing and Cladding Membranes**

Standard roof membranes can cause the death of significant numbers of bats. Traditional bitumen coated roofing felt is recommended where roosting bats are expected to be present.

## The problem

Standard non-bitumen coated membranes (including almost all breathable membranes) used below roof slates and tiles present a significant problem for bats. Over time, strands are pulled away from the surface of these materials as bats crawl over them. These fuzzy strands are very strong and can tangle and trap bats, sometimes causing the death of bats over multiple years<sup>1</sup>.

One example we have encountered comprised a pipistrelle roost which formed in a building extension constructed in 2009. Over the course of just 13 years the roofing felt degraded to the extent that it trapped and killed more than 10 bats. Fortunately, the problem in this roost was identified and remedial work was undertaken to replace the roofing membrane in 2022.



Plate 1. Four dead pipistrelles tangled in breathable roofing membrane

Although a new roof might be considered to lack potential bat access points, that is often not the case. Roofs covered with stone slates almost always have gaps large enough to be accessed by bats, this is often also the case where imitation stone slates are used. On older buildings the uneven roof timbers and/or building design also often results in gaps on wall tops and between slates. Even on new builds it is often possible for bats to access potential roosts via features such as dry verge capping. Some bats can access a space no wider than a biro pen, therefore it is not surprising that they can find their way into most buildings.

## Safe roofing membranes (and membranes behind cladding)

From a bat perspective, the best membrane option for areas where roosts are expected comprises traditional hessian-backed Type 1F bituminous felt. This product has been widely and safely used as a secondary weather barrier since approximately the 1950s/1960s.

<sup>&</sup>lt;sup>1</sup> Wearing S. Essah E., Gunnel K. & Bonser R. (2013) Double jeopardy: the potential for problems when bats interact with breathable roofing membranes in the United Kingdom. Architecture and Environment



Wooden sarking has also been used for many decades and if appropriately treated, is safe for use in bat roosts. Wooden sarking also has the benefit of providing adding additional insulation and is usually breathable.

At the time of writing (and to our knowledge) two products have passed the 'snagging propensity' test; consequently these products are approved by Natural England for use in bat roosts. This test attempts to replicate the wear and tear which results from bats crawling over the membrane. The approved products are: TLX BatSafe<sup>2,3</sup> and SIGA Majcoat 350. Although they have passed this test, it is unclear how these membranes will degrade in the medium and long term, particularly in larger bat roosts. Therefore we do not recommend that they are used for roosts with multiple bats, and particularly for large (maternity roosts). A third product, SIGA Majcoat 200 SOB Diffusion, passed the test for its upper surface only. This product should not be used in known bat roosts or locations where bat mitigation is to be installed. Although none of these products are considered to be as safe as traditional Type 1F bituminous felt, they may provide an option for roofs where future bat use cannot be ruled out, and a breathable solution is required.

## Additional considerations

In recent years a fairly substantial proportion of the lofts we have surveyed which had existing breathable felt, were found to have been damaged by wasps (Plate 2). The wasps appear to have chewed holes in the felt and formed nests. This doesn't appear to be a problem associated with traditional bitumen coated roofing felt. Any holes within roofing felt are likely to significantly reduce its functionality as a secondary weather barrier. Where bats or birds come into contact with breathable roofing membranes, they can also damage it causing it to leak, they can also significantly reduce the breathability of the felt in that location.

#### Plate 2. Damage to a breathable roofing membrane adjacent to a wasp nest



Traditional bituminous Type 1F roofing felt is a non-breathable product and therefore ventilation is required. Sufficient ventilation can be usually be achieved, even in buildings with vaulted ceilings, however, some consideration during the design stage is required. Products to increase the ventilation within roofs where bituminous Type 1F felt has already been installed are also available.

<sup>&</sup>lt;sup>2</sup> <u>https://www.gov.uk/government/publications/bats-apply-for-a-mitigation-licence#full-publication-update-history:~:text=Use%20of%20safe%20roofing%20membranes</u>

<sup>&</sup>lt;sup>3</sup> TLX BatSafe requires all joints and cut edges to be taped in order to prevent the fraying of bare edges.